

School Name: Jesse Wharton Elementary		Report Date(s):	3/11/2020
Date Test Conducted: 2/15/2020		Date Results Received:	2/24/2020
Number of Faucets Tested: 43			
Lead Results		Copper Results	
Results 15 ppb and above:	0	Results 1.3 ppm and above:	1
Results 10 ppb to below 15 ppb:	0	Detectable results below 1.3 ppm:	41
Detectable results below 10 ppb:	0	Results below detection level:	1
Results below detection level:	43		
Number of Faucets Requiring Remedial Action: 1			
Location of Faucet		Action Taken	Date:
Sample ID: JW-001-031-DS-P		<input checked="" type="checkbox"/> Temporarily taken out of service:	2/25/2020
Location Description: JW-001-031-DS-P: drinking station in room 607		<input checked="" type="checkbox"/> Permanently taken out of service:	3/11/2020
		<input checked="" type="checkbox"/> Flush tested:	2/29/2020
		Flush test result: no exceedances	
		<input type="checkbox"/> Replaced:	
		<input type="checkbox"/> Retest:	
		Retest result:	
		Other: _____	
		<input type="checkbox"/> Placed back in service on:	
Daily School-Wide Flushing:			
<input type="checkbox"/> Continue with protocol <input checked="" type="checkbox"/> Discontinue flushing protocol (date): 3/11/20 <input type="checkbox"/> Other (Describe:)			
This is a summary report prepared by Hart & Hickman, PC (H&H). H&H suggests that the full report be referred to with regard to findings, recommendations, and technical limitations for this sampling event.			